

Additional Funding Request

MD021 Winter change over	CSS #16108 WO#6425 Asset # N/A
Description of Repairs	Winter change over
Diagnosis: Initial Work Order CSS# 16108	Winterize chiller barrel
Explanation of Additional Costs for Repairs	Isolate and drain chiller for winter .No Glycol in system
Additional Labor Cost to Perform Repairs	\$250.00= Labor 2.5 hours @ \$100.00 per hour = \$250.00
Additional Material Cost to Perform Repairs	
Total cost	\$250.00