

Additional Funding Request

Submitted: 12/21/20

MD021- Assembly Hall Roll-Up Door	CSS #29108 WO# 13331								
Description of Repairs	SS proposes to remove and replace the chain guard assembly and do a system check to ensure the chain is no longer coming off the gear.								
Original SC Investigative Diagnosis	\$160.00								
Diagnosis: Initial Work Order	Assembly Hall roll-up door chain keeps coming off gear.								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p>Materials: \$98.46</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Chain Guard Assembly</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">\$98.46</td> <td style="text-align: left; padding: 2px;">\$98.46</td> </tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Chain Guard Assembly	1	\$98.46	\$98.46
ITEM	QUANTITY	UNIT PRICE	TOTAL						
Chain Guard Assembly	1	\$98.46	\$98.46						
Additional Labor Cost to Perform Repairs	<p>Labor: \$480.00 General Maint Tech/6 hours/Rate \$80.00 per hour = \$480.00</p>								
Total Cost of Repair	\$738.46								



CUSTOMER QUOTATION NO. 468

CMI Management, Inc.
CMI Management, Inc.
Richard Hicks
5285 Shawnee Road Suite #510
Alexandria VA 22312

Quote Name: 13331
Quote No: 468
Site: MD021 Baltimore Road
Site Contact: Rick Hicks
Salesperson: Lindsay Ruby
Created Date: 12/21/2020
Valid For: 30 Day(s)

WO# 13331

CSS Ticket Number: 28108

Problem: Assembly Hall Roll up door Chain keeps coming off gear.

S&S was onsite and found the chain guide assembly needed to be replaced.
S&S proposes to remove and replace the chain guard assembly and do a system check to ensure the chain is no longer coming off gear.


Service

Item	Quantity	Unit Price	Total
Chain Guard Assembly	1.00	\$73.46	\$73.46
Freight	1.00	\$25.00	\$25.00
Diagnosis Fee	1	\$160.00	\$160.00
General Maintenance Labor Rate	6	\$80.00	\$480.00
		Sub-Total ex Tax	\$738.46
		Tax	\$0.00
		Total inc Tax	\$738.46

Labor	\$640.00
Materials	\$98.46
Sub-Total ex Tax	\$738.46
Tax	\$0.00
Total inc Tax	\$738.46



RE: Chain Kepper



Allison Shelley <ashelley@easternlifttruck.com>

To Lindsay Ruby

 This message has been replied to or forwarded.

Good morning,

So the part is a chain guide \$61.22 Freight will be \$25. I Can

Sincerely,

Allison Shelley

Dock and Door Parts Specialist

Eastern Lift Truck Co., Inc. – Baltimore, MD

