

Additional Funding Request

Submitted: 5/25/21

MD021- Chiller	CSS # 30732 WO#11568								
Description of Repairs	Found Chiller off due to power outage. Reset Chiller into Run Mode. Went through all rooms that were accessible and observed building operation								
Original SC Investigative Diagnosis	NA								
Diagnosis: Initial Work Order	Chiller off line Too Hot in Building								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p>Materials: NA</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;"> </td><td style="text-align: left; padding: 2px;"> </td><td style="text-align: left; padding: 2px;"> </td><td style="text-align: right; padding: 2px;">\$</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL				\$
ITEM	QUANTITY	UNIT PRICE	TOTAL						
			\$						
Additional Labor Cost to Perform Repairs	<p>Labor: \$600.00 6 hours each/Rate \$80.00 per hour = \$480.00</p>								
Total Cost of Repair	\$480.00								