

Additional Funding Request

Submitted: 10/08/2021

MD021- Water Softeners	CSS #32397 WO#15123											
Description of Repairs	S&S proposes to remove and replace (2) timer conversions in the water softeners. S&S will then complete a system check to ensure everything is running properly.											
Original SC Investigative Diagnosis	BILLED UNDER WO 15016 OY3(1000.00)											
Diagnosis: Initial Work Order	Water Softeners need to be serviced, both systems are in Alarm											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	Materials: \$1,864.58 <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="padding: 2px;">Conversion Kit and shipping</td> <td style="padding: 2px; text-align: center;">2</td> <td style="padding: 2px;"></td> <td style="padding: 2px; text-align: right;">\$1,864.58</td> </tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Conversion Kit and shipping	2		\$1,864.58
ITEM	QUANTITY	UNIT PRICE	TOTAL									
Conversion Kit and shipping	2		\$1,864.58									
Additional Labor Cost to Perform Repairs	Labor: Billed under WO 15016 OY3											
Total Cost of Repair	\$1,864.58											