

## Additional Funding Request

Submitted: 09/20/21

<b>MD021 – Fan Motor</b>	<b>CSS # 32509 WO# 15020</b>											
Description of Repairs	S&S proposes to remove and replace the bad fan motor in room 124 asset 2105#30.											
Original SC Investigative Diagnosis	<b>\$150</b>											
Diagnosis: Initial Work Order	Fan motor needs to be replaced Asset 2105#30											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	<b>Materials: \$329.60</b> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;"><b>ITEM</b></th> <th style="text-align: left; padding: 2px;"><b>QUANTITY</b></th> <th style="text-align: left; padding: 2px;"><b>UNIT PRICE</b></th> <th style="text-align: left; padding: 2px;"><b>TOTAL</b></th> </tr> </thead> <tbody> <tr> <td style="padding: 2px;">Motor/120637 with shipping</td> <td style="padding: 2px; text-align: center;">1</td> <td style="padding: 2px; text-align: center;">329.60</td> <td style="padding: 2px; text-align: center;">329.60</td> </tr> </tbody> </table>				<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>	Motor/120637 with shipping	1	329.60	329.60
<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>									
Motor/120637 with shipping	1	329.60	329.60									
Additional Labor Cost to Perform Repairs	<b>Labor: \$400.00</b> 4 hours each/HVAC Rate \$100.00 per hour = \$400.00											
<b>Total Cost of Repair</b>	<b>\$879.60</b>											