

Additional Funding Request

Submitted: **12/07/2021**

MD021- Lighting/Ceiling tiles	CSS #32982 WO#15368								
Description of Repairs	S&S herby proposes to replace (7) 2 lamp ballasts, (14) T8 bulbs and 2 ceiling tiles in rooms 130,129 & 127								
Original SC Investigative Diagnosis	\$200.00								
Diagnosis: Initial Work Order	Rm 130 3x lights 1 ceiling tile. Rm 129 1 light, 1 tile. Rm 127 4 lights.								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p>Materials: \$ 156.66</p> <table border="1"> <thead> <tr> <th>ITEM</th><th>QUANTITY</th><th>UNIT PRICE</th><th>TOTAL</th></tr> </thead> <tbody> <tr> <td>See details in attached Quote</td><td>1</td><td>\$156.66</td><td>\$156.66</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	See details in attached Quote	1	\$156.66	\$156.66
ITEM	QUANTITY	UNIT PRICE	TOTAL						
See details in attached Quote	1	\$156.66	\$156.66						
Additional Labor Cost to Perform Repairs	<p>Labor: \$400.00 4 hours each/Electrical Rate \$100.00 per hour = \$400.00</p>								
Total Cost of Repair	\$756.66								