

Additional Funding Request

Submitted: **12/07/2021**

MD021-Lighting and Ceiling Tiles	CSS #32984 WO#15367								
Description of Repairs	S&S herby proposes to replace (3) 2 lamp ballasts, (6) T8 bulbs and 32 ceiling tiles in rooms 125,124 & 113								
Original SC Investigative Diagnosis	\$150.00								
Diagnosis: Initial Work Order	Rm 125 4 lights, 5 tiles. Rm 124 9 tiles. Lobby, 2 lights, 4 tiles. Rm 113 2 tiles. 12x tiles in kit								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p>Materials: \$ 976.72</p> <table border="1"> <thead> <tr> <th>ITEM</th><th>QUANTITY</th><th>UNIT PRICE</th><th>TOTAL</th></tr> </thead> <tbody> <tr> <td>Details in attached Quote</td><td>1</td><td>\$976.72</td><td>\$976.72</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Details in attached Quote	1	\$976.72	\$976.72
ITEM	QUANTITY	UNIT PRICE	TOTAL						
Details in attached Quote	1	\$976.72	\$976.72						
Additional Labor Cost to Perform Repairs	<p>Labor: \$800.00 8 hours each/Electrical Rate \$100.00 per hour = \$800.00</p>								
Total Cost of Repair	\$1,926.72								