

Additional Funding Request

Submitted: **1/18/21**

MD021-Compressor on Fridge	CSS #33184 WO#16403											
Description of Repairs	S&S further found the compressor is in need of replacement, S&S will remove and replace the compressor then check the system is running correctly											
Original SC Investigative Diagnosis	Done on WO 15385											
Diagnosis: Initial Work Order	Additional Efforts Replace compressor on Fridge											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	Materials: \$ 1,362.98 <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Compressor /161H34 And shipping</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">\$1,362.98</td> <td style="text-align: left; padding: 2px;">\$1,362.98</td> </tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Compressor /161H34 And shipping	1	\$1,362.98	\$1,362.98
ITEM	QUANTITY	UNIT PRICE	TOTAL									
Compressor /161H34 And shipping	1	\$1,362.98	\$1,362.98									
Additional Labor Cost to Perform Repairs	Labor: \$900.00 9 hours each/HVAC Rate \$100.00 per hour = \$900.00											
Total Cost of Repair	\$2,262.98											