

## Additional Funding Request

MD021 Chiller Circuit 2	CSS # 25182 WO# 12320	May 20,2020
Description of Repairs	<p>While onsite performing chiller PMs, S&amp;S found the refrigerant in Circuit # 2 was low.            S&amp;S will add 25lbs of R410A to the system, and check for any possible leaks</p>	
Diagnosis: Initial Work Order CSS# 25182		
Original SC diagnosis	\$300	
Explanation of Additional Costs for Repairs	<p>While onsite performing chiller PMs, S&amp;S found the refrigerant in Circuit # 2 was low.            - S&amp;S will add 25lbs of R410A to the system and check for any possible leaks.</p>	
Additional Labor Cost to Perform Repairs	<p><b>Labor= \$400</b>            - 1 HVAC Tech 4 hours / \$100 an hour</p>	
Additional Material Cost to Perform Repairs	<p><b>Material= \$140.39</b>  <b>Shipping -\$35.00</b>            R410A Refrigerant-<b>\$140.39</b>            Tax= 7.02</p>	
Total	\$882.41	
PM Credit -\$250	-\$250	
Total Cost	<b>Total = \$632.41</b>	