

Additional Funding Request

MD021 Chiller Circuit 2	CSS # 25180 WO# 12318	May 20,2020
Description of Repairs	<p>While onsite performing chiller PMs, S&S diagnosed that the chiller needed a new liquid line drier. S&S will install a new liquid line drier and check the operation to ensure everything is working properly.</p>	
Diagnosis: Initial Work Order CSS# 25180		
Original SC diagnosis	\$0	
Explanation of Additional Costs for Repairs	<p>While onsite performing chiller PMs, S&S diagnosed that the chiller needed a new liquid line drier.</p> <ul style="list-style-type: none"> - S&S will install a new liquid line drier and check the operation to ensure everything is working properly. 	
Additional Labor Cost to Perform Repairs	<p>Labor= \$400</p> <ul style="list-style-type: none"> - 1 HVAC Tech 4 hours / \$100 an hour 	
Additional Material Cost to Perform Repairs	<p>Material= \$57.64</p> <p>Drier Core/ 118558-\$57.64</p> <p>Tax= 2.88</p>	
Total Cost	Total = \$460.52	