

## Additional Funding Request

Submitted: 8/28/2019

<b>MD021 – Fan coil unit</b>	<b>CSS #19798 WO#9607</b>
Description of Repairs	Fan coil unit * 2105FCU #33 Room 126 Valve Off
Original SC Investigative Diagnosis	<b><u>\$100.00</u></b>
Diagnosis: Initial Work Order	S&S proposes to come out and replace the following materials on FCU #33 in room 126. S&S will then do a system check and ensure everything is running properly on unit.
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	<p><b><u>Materials: = \$1,396.60</u></b></p> Controller /222770/ \$1,193.22 Actuator Valves /190760/ \$77.16 Tax: \$76.22 Shipping: \$50.00
Additional Labor Cost to Perform Repairs	<p><b><u>Labor: \$600.00</u></b></p> 1 HVAC Technician/6 Hours/\$100.00 rate = \$600.00
<b>Total Cost of Repair</b>	<b>\$2,096.60</b>