

## Additional Funding Request

Submitted: 8/28/2019

<b>MD021 – Fan coil unit</b>	<b>CSS #19798 WO#9610</b>
Description of Repairs	Fan coil unit-Hall 126 Leak
Original SC Investigative Diagnosis	<b><u>\$100.00</u></b>
Diagnosis: Initial Work Order	<b>S&amp;S proposes to come out and replace the following materials in hall 126. S&amp;S will then do a check and ensure there is no further leaking.</b>
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	<b><u>Materials: \$45.02</u></b> 1/2" 90 Copper Ell/C9D/ \$4.10 Copper Piping /LHARDD10/ \$13.81 1 1/2" Tee /CTD/ \$1.15 Tax: \$0.96 Shipping: \$25.00
Additional Labor Cost to Perform Repairs	<b><u>Labor: \$1,000.00</u></b> 1 HVAC Technician/6 Hours/\$100.00 rate = \$600.00
<b>Total Cost of Repair</b>	<b>\$1,145.02</b>