

Additional Funding Request

Submitted: 8/29/2019

MD021 – Fan coil unit	CSS #19798 WO#9611
Description of Repairs	Fan coil unit * 2105FCO #20 Room 111 B Valve has no resistance
Original SC Investigative Diagnosis	<u>\$100.00</u>
Diagnosis: Initial Work Order	S&S proposes to come out and replace the following materials on FCU #20 in room 111B. S&S will then do a system check and ensure everything is running properly on unit.
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	<u>Materials: = \$1,396.60</u> Controller /222770/ \$1,193.22 Actuator Valves /190760/ \$77.16 Tax: \$76.22 Shipping: \$50.00
Additional Labor Cost to Perform Repairs	<u>Labor: \$600.00</u> 1 HVAC Technician/6 Hours/\$100.00 rate = \$600.00
Total Cost of Repair	<u>\$2,096.60</u>