

## Additional Funding Request

Submitted: 8/30/2019

<b>MD021 – Fan coil unit</b>	<b>CSS #19798 WO#9616</b>
Description of Repairs	Fan coil unit * 2105FCU #11 Room 107 Bad Fan Motor
Original SC Investigative Diagnosis	<b><u>\$100.00</u></b>
Diagnosis: Initial Work Order	S&S proposes to come out and replace the following materials on FCU #11 in room 107. S&S will then do a system check and ensure everything is running properly on unit.
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	<p><b><u>Materials: \$1,287.93</u></b></p> <p>Controller /222770/ \$1,193.22            Relay Board /222775/ \$21.81            Tax: \$72.90</p> <p>Shipping: shipping costs voided, total cost of repairs adjusted</p>
Additional Labor Cost to Perform Repairs	<p><b><u>Labor: \$600.00</u></b></p> <p>1 HVAC Technician/6 Hours/\$100.00 rate = \$600.00</p>
<b>Total Cost of Repair</b>	<b>\$1,987.93</b>