

Additional Funding Request

Submitted: 8/30/2019

| | |
|---|---|
| MD021 – Fan coil unit | CSS #19798 WO#9617 |
| Description of Repairs | Fan coil unit, * 2105FCU #09 Room 107 Bad Fan Motor |
| Original SC Investigative Diagnosis | <u>\$100.00</u> |
| Diagnosis: Initial Work Order | S&S proposes to come out and replace the following materials on FCU #09 in room 107. S&S will then do a system check and ensure everything is running properly on unit. |
| Explanation of Additional Costs for Repairs | N/A |
| Additional Material Cost to Perform Repairs | <p><u>Materials: \$1,346.60</u></p> <p>Controller /222770/ \$1,193.22 Actuator Valves /190760/ \$77.16 Tax: \$76.22</p> <p>Shipping: shipping costs voided, total cost of repairs adjusted</p> |
| Additional Labor Cost to Perform Repairs | <p><u>Labor: \$600.00</u></p> <p>1 HVAC Technician/6 Hours/\$100.00 rate = \$600.00</p> |
| Total Cost of Repair | \$2,046.60 |