

Additional Funding Request

Submitted: 8/31/2019

MD021 – Fan coil unit	CSS #19798 WO#9618
Description of Repairs	Fan coil unit, * 2105FCU #28 Room 113 Fan not working
Original SC Investigative Diagnosis	<u>\$100.00</u>
Diagnosis: Initial Work Order	S&S proposes to come out and replace the following materials on FCU #28 in room 113. S&S will then do a system check and ensure everything is running properly on unit.
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	<u>Materials: \$1,287.93</u> Controller /222770/ \$1,193.22 Relay /222775/ \$21.81 Tax: \$72.90 Shipping: shipping costs voided, total cost of repairs adjusted
Additional Labor Cost to Perform Repairs	<u>Labor: \$600.00</u> 1 HVAC Technician/6 Hours/\$100.00 rate = \$600.00
Total Cost of Repair	\$1,987.93