

## Additional Funding Request

Submitted: 9/3/2019

<b>MD021 – Fan coil unit</b>	<b>CSS #19798 WO#9618</b>
Description of Repairs	Fan coil unit, * 2105FCU #28 Room 113 Fan not working
Original SC Investigative Diagnosis	<b><u>waived</u></b>
Diagnosis: Initial Work Order	<b>S&amp;S proposes to come out and replace the following materials on FCU #28 in room 113. S&amp;S will then do a system check and ensure everything is running properly on unit.</b>
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	<p><b><u>Materials: \$1,287.93</u></b></p> <p>Controller /222770/ \$1,193.22            Relay /222775/ \$21.81            Tax: \$72.90</p> <p>Shipping: shipping costs voided, total cost of repairs adjusted</p>
Additional Labor Cost to Perform Repairs	<p><b><u>Labor: \$600.00</u></b></p> <p>1 HVAC Technician/6 Hours/\$100.00 rate = \$600.00</p>
<b>Total Cost of Repair</b>	<b>\$1,887.93</b>