

Additional Funding Request

Submitted: 9/3/2019

MD021 – Fan coil unit	CSS #19798 WO#9619
Description of Repairs	Fan coil unit,* 2105FCU # 42 No Fan
Original SC Investigative Diagnosis	<u>Waived</u>
Diagnosis: Initial Work Order	S&S proposes to come out and replace the following materials on FCU #42 in room 201. S&S will then do a system check and ensure everything is running properly on unit.
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	<p><u>Materials: \$1,287.93</u></p> <p>Controller /222770/ \$1,193.22 Relay /222775/ \$21.81 Tax: \$72.90</p> <p>Shipping: shipping costs voided, total cost of repairs adjusted</p>
Additional Labor Cost to Perform Repairs	<p><u>Labor: \$600.00</u></p> <p>1 HVAC Technician/6 Hours/\$100.00 rate = \$600.00</p>
Total Cost of Repair	\$1,887.93