

Additional Funding Request

Submitted: 9/3/2019

MD021 – Fan coil unit	CSS #19798 WO#9620
Description of Repairs	Fan coil unit,* 2105FCU #49 No Drip Tray
Original SC Investigative Diagnosis	<u>Waived</u>
Diagnosis: Initial Work Order	S&S proposes to come out and replace the following materials on FCU #49 in hall 204. S&S will then do a system check and ensure everything is running properly on unit.
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	<u>Materials: \$307.11</u> Motor QTY 1 /222836/ \$204.00 Housing QTY 1 /222837/ \$85.72 Tax: \$17.38 Shipping: shipping costs voided, total cost of repairs adjusted
Additional Labor Cost to Perform Repairs	<u>Labor: \$600.00</u> 1 HVAC Technician/6 Hours/\$100.00 rate = \$600.00
Total Cost of Repair	\$907.11