

Additional Funding Request

Submitted: 9/3/2019

MD021 – Fan coil unit	CSS #19798 WO#9623
Description of Repairs	Fan coil unit,* 2109FCU #26 Bad Fan + Valve
Original SC Investigative Diagnosis	<u>Waived</u>
Diagnosis: Initial Work Order	S&S proposes to come out and replace the following materials on FCU #26. S&S will then do a system check and ensure everything is running properly on unit.
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	Materials: \$388.89 Motor QTY 1/222836/ \$204.00 Housing QTY 1/222837/ \$85.72 Actuator Valves /190760/ \$77.16 Tax: \$22.01 Shipping: \$50.00 shipping costs voided, total cost of repairs adjusted
Additional Labor Cost to Perform Repairs	Labor: \$600.00 1 HVAC Technician/6 Hours/\$100.00 rate = \$600.00
Total Cost of Repair	\$988.89