

Additional Funding Request

MD021 FCU 111A	CSS #25179 WO# 12317	May 20,2020
Description of Repairs	While onsite performing chiller PMS, S&S diagnosed that FCU in room 111A needed a new temperature sensor. S&S will remove and replace the temperature sensor and check the operation to ensure everything is working properly.	
Diagnosis: Initial Work Order CSS# 25179	Temp water sensor needs replaced	
Original SC diagnosis = \$0	S&S diagnosed	
Explanation of Additional Costs for Repairs	While onsite performing chiller PMS, S&S diagnosed that FCU in room 111A needed a new temperature sensor. - S&S will remove and replace the temperature sensor and check the operation to ensure everything is working properly.	
Additional Labor Cost to Perform Repairs	Labor= \$400 - 1 HVAC Tech 4 hours / \$100 an hour	
Additional Material Cost to Perform Repairs	Material= \$32.34 1-Temperature Sensor/ 233241 Tax= \$1.62	
Total Cost	Total = \$433.96	