

Additional Funding Request

MD021 FCU 215	CSS # 25181 WO# 12319	May 20,2020
Description of Repairs	<p>While onsite performing chiller PMs, S&S diagnosed that FCU in room 215 needed a new temperature sensor.</p> <p>S&S will remove and replace the temperature sensor and check the operation to ensure everything is working properly.</p>	
Diagnosis: Initial Work Order CSS# 25181	Temp water sensor needs replaced	
Original SC diagnosis = \$0	S&S diagnosed	
Explanation of Additional Costs for Repairs	<p>While onsite performing chiller PMs, S&S diagnosed that FCU in room 215 needed a new temperature sensor.</p> <ul style="list-style-type: none"> - S&S will remove and replace the temperature sensor and check the operation to ensure everything is working properly. 	
Additional Labor Cost to Perform Repairs	<p>Labor= \$400</p> <ul style="list-style-type: none"> - 1 HVAC Tech 4 hours / \$100 an hour 	
Additional Material Cost to Perform Repairs	<p>Material= \$32.34</p> <p>1-Temperature Sensor/ 233241</p> <p>Tax= \$1.62</p>	
Total Cost	Total = \$433.96	