

## Additional Funding Request

<b>MD021 Fan Motor</b>	<b>CSS #15656 WO# 5997 / 6015</b>
Description of Repairs	S&S will remove and replace fan motor found bad near room 101
Diagnosis: Initial Work Order <b>CSS# 15656</b>	[Ken Augustin] Circulation fan not working in 101.
Explanation of Additional Costs for Repairs	S&S will remove and replace fan motor found bad near room 101
Additional Labor Cost to Perform Repairs	1 HVAC Technician /3hours/ Rate \$100.00 per hour = \$300.00
Additional Material Cost to Perform Repairs	Materials: = \$299.55  Fan Motor = \$261.48  Tax = \$13.07  Shipping: \$25.00
<b>Total Cost</b>	<b>\$599.55</b>