

## Additional Funding Request

MD021 No A/C Reported	CSS # 25990 WO# 12573	July 22,2020
Description of Repairs	<p>S&amp;S proposes to remove and replace the fan motor assembly and actuators on FCU 49 &amp; 70.            S&amp;S will then complete a system check to ensure everything is running as intended.</p>	
Diagnosis: Initial Work Order CSS# 25990	No A/C Reported in Building	
Original SC diagnosis	\$300	
Explanation of Additional Costs for Repairs	<p>S&amp;S proposes to remove and replace the fan motor assembly and actuators on FCU 49 &amp; 70.</p> <ul style="list-style-type: none"> <li>- S&amp;S will then complete a system check to ensure everything is running as intended.</li> </ul>	
Additional Labor Cost to Perform Repairs	<p><b>Labor= \$900</b></p> <ul style="list-style-type: none"> <li>- 1 HVAC Tech 9 hours / \$100 an hour</li> </ul>	
Additional Material Cost to Perform Repairs	<p><b>Material= \$668.69</b></p> <p>Actuator/ 190760 (2.00) @ \$92.18 = \$184.36            Motor / 152182 (1.00) @ \$326.34 = \$326.34            Surge Protector 1 \$107.99 \$107.99</p>	
Total Cost	<b>Total = \$1,868.69</b>	