

Additional Funding Request

Submitted: 3/3/2022

MD021	CSS #34684 WO#16760
Description of Repairs	S&S found BAS is not reading temp correctly, S&S proposes to remove and replace the Trane return water temperature sensor. S&S will then complete a system check to ensure everything is working properly. <i>*Part has a 3 day lead time..</i>
Diagnosis: Initial Work Order	(BAC) -Building automation computer is not reading equip
Explanation of Additional Costs for Repairs	S&S found BAS is not reading temp correctly, S&S proposes to remove and replace the Trane return water temperature sensor. S&S will then complete a system check to ensure everything is working properly. <i>*Part has a 3 day lead time.</i>
Investigative Diagnosis fee from SC	\$300
Additional Material Cost to Perform Repairs	Trane sensor \$34.04 + \$25 shipping
Additional Labor Cost to Perform Repairs	Labor: \$800 1 HVAC Technician/8 Hours/\$100.00 rate= \$800.00
Total Cost	\$1,159.04