

Additional Funding Request

MD021 Water leak behind wall	CSS #20803 WO#10593 Asset # N/A
Description of Repairs	S&S proposes to come out and replace the following materials for room 125A women shower area. S&S will then do a system check and ensure there is no further leaking
Diagnosis: Initial Work Order CSS# 20803	Water leak found behind sheetrock
Explanation of Additional Costs for Repairs	S&S proposes to come out and replace the following materials for room 125A women shower area. S&S will then do a system check and ensure there is no further leaking
Investigative Diagnosis from SC	\$250.00
Additional Labor Cost to Perform Repairs	Labor: \$900.00 1 General Maintenance Technician/12 Hours/\$75.00 rate= \$900.00 Full estimated
Additional Material Cost to Perform Repairs	Materials: \$298.99 4 1/8 Pipe Insulation /JI53418/ \$66.00 1 5/8 Pipe Insulation /JI53158/ \$17.76 7/8 Wall Insulation/JI53078/ \$11.36 #5 Insulation 90 Ell/FI9S/ \$12.26 #13 Insulation Tee/SP-FIT13/ \$24.00 #7 Insulation Tee/FITW/ \$9.19 #5 Insulation Tee/FITS/ \$7.30 Insulation Tape/VI540CW/ \$41.65 Shipping: \$100.00 Tax: \$9.47
Total direct cost	\$1,448.99