

Additional Funding Request

Submitted: 6/19/2019

MD021 – air compressor	CSS #18966 WO#8835
Description of Repairs	Air compressor will not start after air is used, starter motor relay may need replaced.
Original SC Investigative Diagnosis	\$1,118.00
Diagnosis: Initial Work Order	<p>S&S proposes to furnish the labor and material necessary for the completion of the following</p> <ul style="list-style-type: none"> - S&S will remove and replace bad high-pressure discharge valve with needed gasket and o-ring on compressor head. - Work will take place during normal business hours.
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	<p>Material: \$236.38</p> <p>Discharge valve \$223.00 Tax: \$13.38</p>
Additional Labor Cost to Perform Repairs	<p>Labor: \$600.00</p> <p>2 Technicians /3 hours/ Rate \$100.00 per hour = \$600.00</p>
Total Cost of Repair	\$1,954.38