

Additional Funding Request

Submitted: 1/24/2019

MD021 – boiler #3 reinspection	CSS # 17396 WO# 7262
Description of Repairs	Site visit for boiler # 3 reinspection at MD021 by Argent Inspections, Inc.
Original SC Investigative Diagnosis	N/A
Diagnosis: Initial Work Order	S&S to provide operational support to Argent Inspectors.
Explanation of Additional Costs for Repairs	Argent fee for boiler #3 reinspection \$1,247.10
Additional Material Cost to Perform Repairs	Materials: N/A
Additional Labor Cost to Perform Repairs	Labor: \$400.00 S&S operational support... 1 HVAC Technician/4 hours/ Rate \$100.00 per hour = \$400.00
Total Cost of Repair	\$1,647.10