

Additional Funding Request

Submitted: 2/25/2019

MD021 – ignition module radiant heater	CSS #16922 WO#7145/New WO 7976 Asset# 2106
Description of Repairs	S&S was onsite to install parts needed for the radiant heaters in the drill hall and found that another ignition module was needed.
Diagnosis: Initial Work Order	S&S was onsite to investigate the radiant heaters in the drill hall and found that another ignition module was needed.
Explanation of Additional Costs for Repairs	N/A
Investigative Diagnosis from SC	Waived
Additional Material Cost to Perform Repairs	Materials: \$435.76 Ignition module: \$391.20 Tax: \$19.56 Shipping: \$25.00
Additional Labor Cost to Perform Repairs	Labor: \$300.00 1 HVAC technician/3hours/Rate \$100.00 per hour = \$300.00
Total of Corrective Maintenance Ticket	N/A
Minus \$250 Cost of PM credit	(\$250.00) taken off on WO 7145/CSS16922
Total Cost of Repair	\$735.76