

**Additional Funding Request
Corrective Maintenance from PM**

Submitted: 2/8/2019

MD021 – radiant heaters	CSS #16922 WO#7145 Asset# 2106
Description of Repairs	2-Radiant heaters are not working in drill hall.
Diagnosis: Initial Work Order	S&S was onsite to investigate the radiant heaters in the drill hall. Used a 12 foot ladder to access heaters. Found that one heater needs an ignition module and one heater needs an inducer motor. S&S hereby proposes to return and install a new ignition module and inducer motor for two of the radiant heaters.
Explanation of Additional Costs for Repairs	N/A
Investigative Diagnosis from SC	\$550.00
Additional Material Cost to Perform Repairs	Materials: \$891.88 Ignition module: \$391.20 Inducer motor: \$434.40 Tax: \$41.28 Shipping: \$25.00
Additional Labor Cost to Perform Repairs	Labor: \$600.00 1 HVAC Technician/6hours/ Rate \$100.00 per hour = \$600.00
Total of Corrective Maintenance Ticket	\$2,041.88
Minus \$250 Cost of PM credit	(\$250.00)
Total Cost of Repair	\$1,791.88