

Additional Funding Request

Submitted: 3/3/2022

MD066	CSS #34745 WO#16766
Description of Repairs	S&S proposes to remove and replace the Taco high pressure vent on the Air Separator in the Boiler room. S&S will then complete a system check to ensure everything is running properly. <i>*Parts had 3-4 day lead time.</i>
Diagnosis: Initial Work Order	Repair Air Separator in Boiler room its leaking
Explanation of Additional Costs for Repairs	S&S proposes to remove and replace the Taco high pressure vent on the Air Separator in the Boiler room. S&S will then complete a system check to ensure everything is running properly. <i>*Parts had 3-4 day lead time.</i>
Investigative Diagnosis fee from SC	\$250
Additional Material Cost to Perform Repairs	Air vent \$ 630.00 + \$75 shipping
Additional Labor Cost to Perform Repairs	Labor: \$600 1 HVAC Technician/6 Hours/\$100.00 rate= \$600.00
Total Cost	\$1,555.00