

### **Additional Funding Request**

Submitted: 11/14/2019

<b>MD066 – boiler certification</b>	<b>CSS #22492 WO #11301</b>
Description of Repairs	Boiler certification needed, scheduled November 15, 2019.
Diagnosis: Initial Work Order	S & S proposes to remove and install a new blocked flu switch on the boiler located at MD066. S & S will then do an operation check and ensure everything is operating correctly for the Boiler Certification.
Diagnostic Fee	<b>Diagnostic Total: NA</b>
Explanation of Additional Costs for Repairs	NA
Additional Labor Cost to Perform Repairs	<b>Labor: \$900.00</b> HVAC Labor Rate /9 hours/ Rate \$100.00 per hour = \$900.00
Additional Material Cost to Perform Repairs	<b>Materials: \$80.44</b> Material (see attached detail)
<b>Total Cost of Repair</b>	<b>\$980.44</b>