

## Additional Funding Request

Submitted: 4/15/2021

<b>MD066-Urinal</b>	<b>CSS #30083 WO# 13988</b>		
Description of Repairs	After trying to change the batteries in the automated valve that did not fix the issue. There seems to be some type of electrical connection that is corroded. S&S proposes to remove and replace the automatic Sloan flush valve. S&S will then check to ensure the urinal is now fully operational.		
Original SC Investigative Diagnosis	<b>\$300.00</b>		
Diagnosis: Initial Work Order	NR 2nd floor Men's Room Urinal needs repaired-Not flushing		
Explanation of Additional Costs for Repairs	N/A		
Additional Material Cost to Perform Repairs	<b>Materials: \$534.53</b>		
	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>
	Sloan Flush Valve	1	\$434.53
	Shipping	1	\$100.00
Additional Labor Cost to Perform Repairs	<b>Labor: \$400.00</b> Plumber Labor Tech/4 hours/Rate \$100.00 per hour = \$400		
<b>Total Cost of Repair</b>	<b>\$1,234.53</b>		