

Additional Funding Request

Submitted: 10/05/2021

MD066 – Outside lighting	CSS # 32691 WO# 15113			
Description of Repairs	S&S will need to return with a lift to further diagnose. S&S will include ballast & wire on the quote in case it can be fixed while onsite.			
Original SC Investigative Diagnosis	\$400.00			
Diagnosis: Initial Work Order	Parking lot lights Asset 373 MEP Lot Parking lot lights Assets 353 & 371			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	Materials: \$1,444.90			
	ITEM	QUANTITY	UNIT PRICE	TOTAL
	Parts, Lift, Shipping (See attached quote for detail)	1	1	1,444.90
Additional Labor Cost to Perform Repairs	Labor: \$1000.00 10 hours each/Electrical Rate \$100.00 per hour = \$1,000.00			
Total Cost of Repair	\$2,844.90			
CM CREDIT	(\$750.00)			
Final Total of Repair	\$2094.90			