

Additional Funding Request

Submitted: 3/15/2022

| MD066 Fan Motor | CSS #34744 WO#16765 | | | | | | | | | | | |
|--|---|-----------------|-----------------|--|------|----------|------------|-------|--|---|-----------------|-----------------|
| Description of Repairs | S&S proposes to remove & replace the fan motor on the Hymn heater. S&S will then complete a system check to ensure everything is running properly. | | | | | | | | | | | |
| Original SC Investigative Diagnosis | \$375.00 | | | | | | | | | | | |
| Diagnosis: Initial Work Order | Repair UH2-193 in boiler room Fan is not working on heater. | | | | | | | | | | | |
| Explanation of Additional Costs for Repairs | N/A | | | | | | | | | | | |
| Additional Material Cost to Perform Repairs | Materials: \$ 335.00 <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Fan Motor 11J3R04766 and shipping</td> <td style="text-align: center; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">\$335.00</td> <td style="text-align: left; padding: 2px;">\$335.00</td> </tr> </tbody> </table> | | | | ITEM | QUANTITY | UNIT PRICE | TOTAL | Fan Motor 11J3R04766 and shipping | 1 | \$335.00 | \$335.00 |
| ITEM | QUANTITY | UNIT PRICE | TOTAL | | | | | | | | | |
| Fan Motor 11J3R04766 and shipping | 1 | \$335.00 | \$335.00 | | | | | | | | | |
| Additional Labor Cost to Perform Repairs | Labor: \$800.00 8 hours each/HVAC Labor rate \$100.00 per hour = \$800.00 | | | | | | | | | | | |
| Total Cost of Repair | \$1,510.00 | | | | | | | | | | | |