

## Additional Funding Request

MD066 OIL Water Separator	CSS # Pending   WO# 12768	August 31,2020
Description of Repairs	Additional funding needed to completely empty the 1500-gallon OWS tank and inspect the tank for proper operation	
Diagnosis: Initial Work Order CSS# pending	Additional funding needed to completely empty the 1500-gallon OWS tank and inspect the tank for proper operation	
Original SC diagnosis	\$0	
Explanation of Additional Costs for Repairs	- Additional funding needed to completely empty the 1500-gallon OWS tank and inspect the tank for proper operation	
Additional Labor Cost to Perform Repairs	-	
Additional Material Cost to Perform Repairs		
Notes; ELIN = \$2909.55 -\$300 Bond tests March = \$2609.55 AEG Total \$4,140.00- \$2,609.55=Balance needed \$1,530.45	Notes; ELIN Funding = \$2909.55 -\$300 Bond tests March = \$2609.55 AEG Total \$4,140.00 for services now -\$2,609.55=Balance needed \$1,530.45 to fund services	
Total Cost	<b>Total = \$1,530.45</b>	