

Additional Funding Request

MD066 Lighting Ballast	CSS # 22766 WO# 11454 Asset # MD66-538
Description of Repairs	Replace ballast in the following areas: (1) One is in the gym. (2) One is in the women's latrine/ locker room next to the gym (3) staircase B near the gym. I have small piece of blue tape on each (4) Room 130
Diagnosis: Initial Work Order CSS# 22766	Replace ballast in the following areas: (1) One is in the gym. (2) One is in the women's latrine/ locker room next to the gym (3) staircase B near the gym. I have small piece of blue tape on each (4) Room 130
Explanation of Additional Costs for Repairs	S & S proposes to furnish and install the following: S & S will remove the bad ballast in all the above locations. S & S will then install new ballasts and check the operation to ensure it working properly. .
Diagnosis Fee	\$350.00
Additional labor	\$800 – Electrician 8 hours @ 100 per hour
Additional Material Cost to Perform Repairs	\$393.36-Ballast and battery pack
Sub total	\$1543.36
-\$250 PM credit	\$250
Total cost	\$1293.36