

## **Additional Funding Request**

Submitted: 11/14/2019

<b>MD066 – water heater inspection</b>	<b>CSS #22492 WO #11301</b>
Description of Repairs	Site visit to inspect additional water heater; not captured in inventory.
Diagnosis: Initial Work Order	Site visit to inspect additional water heater, travel expenses, preparation and submission of paperwork. Performed by Argent Inspections.
Diagnostic Fee	<b>Diagnostic Total: NA</b>
Explanation of Additional Costs for Repairs	NA
Additional Labor Cost to Perform Repairs	<b>Labor: \$300.00</b>
Additional Material Cost to Perform Repairs	NA
<b>Total Cost of Repair</b>	<b>\$300.00</b>