

**Additional Funding Request
With Invoice**

Submitted: 4/6/2021

MD099-2018 Upgrade Controller Firmware	CSS #29927 WO# 13975							
Description of Repairs	<p>- Trane Tracer SC-01 Deleted users no longer accessing Building Controller and added new users. Upgraded controller firmware and backed up building controller.</p>							
Original SC Investigative Diagnosis	\$486.00							
Diagnosis: Initial Work Order	Upgraded controller firmware and backed up building controller.							
Explanation of Additional Costs for Repairs	N/A							
Additional Material Cost to Perform Repairs	<p>Materials: N/A</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL
ITEM	QUANTITY	UNIT PRICE	TOTAL					
Additional Labor Cost to Perform Repairs	Labor: N/A							
Total Cost of Repair	\$486.00							