



Proudly serving the entire states of Virginia & North Carolina.

Altavista, VA • Charlottesville, VA • Chesapeake, VA • Manassas, VA
Lynchburg, VA • Richmond, VA • Raleigh, NC • Charlotte, NC

P.O. Box 119 • Altavista, VA • 800.789.7199 • service@mooreselectric.com

Billing Address	Site Address
Customer: TIDEWATER, INC Address: 6625 SELNICK DRIVE ELKRIDGE MD 21075 Phone: 614-623-9569	Customer: USARC VA099 BEDFORD Address: 1117 HARMONY LANE BEDFORD VA 24523 Phone: 614-623-9569
Service Call #: COM0165032	Call Type: COM-HVAC


Service Requested
HWB-2 GAS ODOR 10.15.21 ST QUOTE SUBMITTED PARTS NEED ORDERING 10/18 LK: QUOTE APPROVED \$1,638.52 1 MAN @ 8 HOURS DESCRIPTION OF REPAIRS: Moore's is proposing to remove and install new gas valve. Will start, test, and ensure proper operation. 10/18 LK: Work scheduled for 10/26 @ 9 am

Problems					
Description	Tech	Equip. Desc and Model	Manufacturer	Equip. Serial	Asset ID
BOILER DOWN OR NOT OPERATING	HOWARDFLOYD	LOCHINVAR - HWB-2 MN: KBN400	LOCHINVAR	K12H10234406	2360

Tech Notes
Tech: HOWARD FLOYD, Date: 10/14/21 During inspection, I found that the gas valve was weeping LP gas through the valve. Proposal submitted. NO LABOR THIS DAY. Tech: HOWARD FLOYD, Date: 10/26/21 Picked up gas valve and on site, I checked in with AR upon arrival, whom unlocked the Mechanical Rm. 110 for me to access the boiler. At the boiler, I unwired the gas valve, and control panel; removed control panel and mounting supports and panels, then removed the gas piping to the gas valve and the air intake tube piping and rubber reducing coupling connectors. Removed/replaced the gas valve, had to reorient the 'venturi' position, 180 degrees to fit the inducer housing. Transferred the pressure switch sensing tube fitting from the old valve to the new valve. Connected the gas piping, wiring, sensing tubes and fresh air intake and couplers. System has been turned off and the ignitor had been removed, preparatory to the arrival of the inspector next week. Signed out with the reserve personnel. THIS REPAIR W.O. IS COMPLETE.

Labor			
Date	Technician	Description	Hours
10/26/2021	HOWARD FLOYD	REGULAR HEAVY COMMERCIAL LABOR	7.00

Materials			
Date	Part Number	Description	Quantity
10/18/2021	CMISCX-NON-STOCK ITEM	Items for PO 270379	1.000
10/25/2021	CMISCX-NON-STOCK ITEM	LOCHINVAR 100172006 Gas Valve Ass'y (PO 270379)	1.000
10/25/2021	CMISCX-NON-STOCK ITEM	LOCHINVAR 100172006 Gas Valve Ass'y - TAX (PO 270379)	1.000
10/25/2021	CMISCX-NON-STOCK ITEM	LOCHINVAR 100172006 Gas Valve Ass'y - FREIGHT (PO 270379)	1.000
10/26/2021	COISLS-BLUE RAG	BLUE RAG - EACH	1.000
10/26/2021	CPVCP-PIPE DOPE USE	PIPE DOPE USE	1.000
10/26/2021	CMISCX-NON-STOCK ITEM	PARTS ORDER	1.000

Signed By	Signature	Date
Sgt. Timothy Romer		10/26/2021