

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

EXHAUST BLOWER/CONNECTION

SITE AND BLDG #: NY023-121

LOCATION/RM #: Building 121

MECHANIC SIGNATURE: Deen Rowe

DATE: 6/2/21

START TIME: 2pm

INISH TIME: 4pm

Site Location	WO #	Asset #	PM #	Manufacturer	Model Number	Serial #	Asset Description	Asset Location
NY023-121	13082	9333	PM-QT-9333				J-57 1-pc Exhaust Blower	
NY023-121	13083	9334	PM-QT-9334				J-57 5-pc Exhaust Connection	
NY023-121	13084	9335	PM-QT-9335				J-57 1-pc Exhaust Blower	
NY023-121	13085	9336	PM-QT-9336				J-57 6-pc Exhaust Connection	

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS 1 TASK COMPLETE IS CHECKED NO PROVIDE EXPLANATION
		YES	NO	
SPECIAL INSTRUCTIONS				
	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.	✓	/	
2	Schedule shutdown with operating personnel, as needed.	✓	/	
3	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.	✓	/	
TO BE PER ORMED AT EACH INSPECTION SERVICE				
	Clean unit, especially fan blades.	✓	/	
2	Inspect pulleys, belts, couplings, etc.; adjust tension and tighten mountings as necessary. Change badly worn belts. Multiple belts should be replaced with matched sets.	✓	/	
3	Perform required lubrication and remove old or excess lubricant.	✓	/	

4	Clean motor with vacuum or low pressure dry air (less than 40 psi). Check for obstructions in motor cooling and air flow.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
5	Check structural members, vibration eliminators, and flexible connections. Check fan housing to ensure there is no damage and the housing is tight.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
6	Start unit and check for vibration and noise.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
7	Remove all trash and debris.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

- * 2 trailers in the middle of B.121 don't have access to Asset # 9333.
- * two of Asset # 9334 are not connected.

