

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
VEHICLE EXHAUST REMOVAL

SITE AND BLDG #: NY023-123

LOCATION/RM #: Vehicle Area

MECHANIC
SIGNATURE: Den Rose

DATE: 12/17/19

START TIME: 8:00am

FINISH TIME: 1:00pm

Site Location	WO #	Asset #	PM #	Manufacturer	Model Number	Serial #	Asset Description	Asset Location
NY023-123	6234	9385	PM-QT-9385	Plymovent			J-57 1-pc Overhead Exhaust System	
NY023-123	6235	9386	PM-QT-9386	Plymovent			J-57 1-pc Overhead Exhaust System	
NY023-123	6236	9387	PM-QT-9387	Plymovent			J-57 1-pc Overhead Exhaust System	
NY023-123	6237	9388	PM-QT-9388	Plymovent	3 drops per system		J-57 2-pc Overhead Exhaust System	

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)	
		YES	NO	SPECIAL INSTRUCTIONS	
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered.		<input checked="" type="checkbox"/>		
2	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.		<input checked="" type="checkbox"/>		

TO BE PERFORMED AT EACH INSPECTION SERVICE

1	Start and stop fan with local switch		
2	Check motor and fan shaft bearings for noise, vibration, overheating; lubricate bearings.		
3	Inspect, adjust belts and pulleys. Replace belt as needed.		
4	Clean dampers; lubricate pivot points (annually) and inspect linkages for tightness.		
5	Inspect fan for bent blades, unbalance, excessive noise and vibration.		
6	Clean fan as needed.		
7	Visually inspect exhaust system tubing and/or duct work for any damage that could result in leaks.		
8	Repair as needed		

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

Units Are too high to reach

