

**PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST**  
**PLUMBING FIXTURES**

ACTIVITY AND BLDG #: NY023-319

MECHANIC  
SIGNATURE:

*Mychale Wolfe*

DATE:

*2/1/19*

LOCATION:

START TIME:

*7am*

FINISH TIME:

*2pm*

Site Location	WO #	Asset #	PM #	Manufacturer	Model Number	Serial #	Asset Description	Asset Location
NY023-319	4424	9539					J-26 3-pc Toilet, Flush Valve, Floor Mounted Rm A010	
NY023-319	4425	9540					J-26 3-pc Lavatory, Wall Mounted Rm A010	
NY023-319	4426	9541					J-26 3-pc Urinal, Wet, Flush Valve Rm A010	
NY023-319	4427	9542					J-26 2-pc Shower, Built-In Rm A010	
NY023-319	4428	9543					J-26 3-pc Lavatory, Wall Mounted Rm 1008	
NY023-319	4429	9544					J-26 2-pc Shower, Built-In Rm 1008	
NY023-319	4430	9545					J-26 2-pc Toilet, Flush Valve, Floor Mounted Rm 1008	

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
SPECIAL INSTRUCTIONS				

1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered.			
2	Review manufacturer's instructions.			
3	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.			
<b>TO BE PERFORMED AT EACH INSPECTION SERVICE</b>				
1	SINKS - Operate faucets, inspect for leaks, replace washers/"O" rings as necessary. Observe drain flow, clean trap if obstructed. Replace filter as needed.			
2	SHOWER HEADS, MIXING VALVES - Check shower for damaged, missing, or leaking heads; replace as required. Check mixing valves for damaged or missing parts; replace washers as needed.			
3	SHOWER STALLS - Check for leaks, cracks, significant wear or vandalism.			
4	TOILETS - Flush and adjust water flow if required. Inspect for leaks, missing or damaged parts/caps, seat supports, and replace.			
5	URINALS - Flush and adjust water flow if required. Inspect for leaks, missing or damaged parts/caps and replace.			
6	OTHER MISCELLANEOUS FIXTURES - Clean and inspect for any damage. Check for leaks, missing or damaged parts, caps, etc. Replace as needed.			

Note: The Contractor shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence.

Checklist compiled in accordance with:

- Original equipment manufacturers (OEM) documentation for exact or similar assets, which can be located at ([Provide Link to OEM Manual/Asset Library](#))

**Additional Notes:**

