

Additional Funding Request

Site: NY023	WO# 17193 CSS172
Description of Repairs	Remove broken door and replace with custom dutch door. Remove existing door and replace with a 36" dutch door. Panint door and molding to match existing colors.
Diagnosis: Initial Work Order	Install Dutch door in computer office of building # 206
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8 total man hours @ 155.00 hr = \$1240.00
Additional Material Cost to Perform Repairs	\$675.00
Total Cost of Repair	\$1915.00

ACAV SERVICES

April 28, 2022



ESTIMATE 042822 CSS172 WO17193

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 206)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY23 BLDG 206</p> <p>REMOVE BROKEN DOOR AND REPLACE WITH CUSTOM DUTCH DOOR</p> <p>REMOVE EXISTING DOOR AND REPLACE WITH a 36" "DUTCH DOOR"</p> <p>PAINT DOOR AND MOLDINGS TO MATCH EXISTING COLORS</p> <p><u>MATERIAL</u></p> <p>1EA SOLID CORE 36" WOOD "DUTCH" DOOR</p> <p>PRIMER, PAINT CAULK AND HARDWARE</p>		\$675.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		LABOR 8 HRS @ \$155.00 PER HOUR (2 MEN 4 HRS EACH) TOTAL		\$1240.00
		TOTAL		\$1915.00
				TOTAL \$1915.00