

Additional Funding Request

Site: NY023	WO# 3176 CSS # 17732 Asset# NA
Description of Repairs	Repair both upper and lower entry key pads at the entrance to MEP lot.
Diagnosis: Initial Work Order CSS# 17732	Repair both upper and lower entry key pads at the entrance to MEP lot.
Explanation of Additional Costs for Repairs	Investment is labor and materials to repair both upper and lower entry key pads at the entrance to MEP lot.
Additional Labor Cost to Perform Repairs	NTE \$1,450.00
Additional Material Cost to Perform Repairs	
Total Cost of Repair	NTE \$1,450.00

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Invoice

BILL TO

Louis Corbo

INVOICE # 1382

DATE 03/05/2019

DUE DATE 04/04/2019

TERMS Net 30

P.O. NUMBER

Ft. Totten, NY AMSA Shop Reader

ACTIVITY	QTY	RATE	AMOUNT
Services As per Estimate #1334:	1	550.00	550.00

Dear Mr. Corbo:

After investigation found Access Control System to be disconnected by others (possibly by G6 while working on Switch).
Reconnected Galaxy Panels, reloaded Software and tested for proper operation.
Found Door to be out of adjustment; readjusted Door for proper operation.
System functioning 100% at the time of departure.

The cost for this work is \$550.00.

Ft. Totten, NY USARC AMSA Shop
Diagnose Repair/Replace Reader

Dear Mr. Corbo:

As per your request, LoCurrent Systems is pleased to diagnose and repair/replace nonfunctioning Card Reader at Ft. Totten, NY AMSA Shop while on site for the Ft. Totten, NY CCTV Service Call (Estimate #1262).

The cost for the above mentioned work is based on service being performed in the same trip as Ft. Totten CCTV Service (Est.1262) and shall not exceed \$1,450.00.

If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed.

Thank you for thinking of LoCurrent Systems.

Sincerely,

Antonietta LoRusso

If you have any questions regarding this invoice, please contact Antonietta LoRusso at (607)293-7300.

BALANCE DUE

\$550.00