

Additional Funding Request

Site: NY023	WO# 3412	CSS # 18394	Asset# NA
Description of Repairs	Repair and recoat gutter seam at front of Building. Inspect roof		
Diagnosis: Initial Work Order CSS# 18394	Fix gutter leak above loading dock door and leaking roof		
Explanation of Additional Costs for Repairs	Labor and material to Repair and recoat gutter seam at front of Building. Inspect roof		
Additional Labor Cost to Perform Repairs	$3 \times \$190.00 = \570.00		
Additional Material Cost to Perform Repairs	\$70.00		
Total Cost of Repair	\$640.00		

ACAV SERVICES

October 3, 2019



ESTIMATE 1003193 CSS 18394

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC DPW R Linn
Customer ID#	NY023 (BLDG 124)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	October 15, 2019
Salesperson	JW	Shipping Method	N/A
Payment Terms	CC	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	BUILDING 124 REPAIR AND RECOAT GUTTER SEAM AT FRONT OF BUILDING INSPECT ROOF Labor 3 hrs @ \$190.00 per hour		\$570.00
		Material		\$70.00
		TOTAL		\$640.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581