

Additional Funding Request

Site: NY023	CSS # 18944 WO-2-3679
Description of Repairs	Replace defective faucet with Delta 8" Spread single handle
Diagnosis: Initial Work Order CSS# 18944	Door knob fell off S2 office, room #3004C, third floor of building 200
Explanation of Additional Costs for Repairs	Labor and Material to Replace defective faucet with Delta 8" Spread single handle
Additional Labor Cost to Perform Repairs	$9 \times \$105.00 = \945.00
Additional Material Cost to Perform Repairs	\$956.00
Total Cost of Repair	\$1901.00
Notes:	Best mortise lock body room 1037B Hours to install lock body room 103 7B Cipher lock w/ DOD security requirements room 1004C Padlock for Cipher lock room 1004C IC core knob lock less core room 1004C Hours labor to install locks on room 1004C Strike plate for Cipher lock room 3012 Padlock for Cipher lock room 3012 Hours labor to remove Cipher lock, decipher combo and set new combo and install strike plate room 3012 Hours labor to install cores and forks in rooms 3012A, 3012B, 3012D