

## Additional Funding Request

<b>Site:</b>	<b>WO #23341 CSS #93991</b>
Description of Repairs	Air Conditioner is down in NOC room causing router to overheat and shutoff internet to entire facility Date Sent: 6/16/23
Diagnosis: Initial Work Order	recover Freon from system; disconnect electrical; check electrical for shorts; disconnect refrigerant lines; remove old condenser; install new condenser; connect copper lines; connect electrical; pressurize with nitrogen and check for leaks; vacuum system; charge the system with 410A Freon; check operation.
Explanation of Additional Costs for Repairs	Further repair of a leak found in the pressurized cooling line
Additional Labor Cost to Perform Repairs	420.00
Additional Material Cost to Perform Repairs	95.00
Total Cost of Repair	515.00

# ACAV SERVICES

July 7, 2023



ESTIMATE 062123A CSS93991 WO23318 (REPAIR)  
PO10004-1050

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 200)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p><b>NY23 (BLDG 200) NOC ROOM REPLACED TRANE XR 4 TON CONDENSER MODEL 34TWR7048A100BA</b></p> <p><b>WHILE REPLACING THE CONDENSER A LEAK IN THE REFRIGERANT LINE WAS DISCOVERED</b></p> <p><b><u>MATERIAL</u></b></p> <p><b>1EA TANK NITROGEN</b></p> <p><b><u>LABOR</u></b></p> <p><b>2 HRS @ \$210.00 PER HOUR</b></p> <p><b>TOTAL</b></p>		<p><b>\$95.00</b></p> <p><b>\$420.00</b></p> <p><b>\$515.00</b></p>

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581



