

Over and Above Estimate

Region: 2

Location: NY023

CSS #: 94490

Maximo Work Order No. 23767

Asset#:

Date Issued: 07/25/2023

Original Description: AC blower is not functioning in the 1st floor meeting room. Need to diagnose the issue with ACCU 1A & 1B.

Description of Repairs: Weld all lines; replace condenser; vacuum system; recharge system with 410A; replace air filters in the evaporator coil; acid wash and rinse condenser coil; acid wash and rinse evaporator coil

Non Pre-Priced Estimate:

Quantity	Line Item #	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$6275.00	\$	\$6275.00

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material	Equipment Cost	Total Cost	CE Factor	Total Estimate
(3 men @ 8 hrs/ea) <u>24 @ 205.00</u> = \$4920.00	\$4920.00	\$6275.00	\$	\$11195.00	1.02	\$11418.90

Please see attached estimate

ACAV SERVICES

July 27, 2023



ESTIMATE 072623 CSS94229 WO23339
PO100041054

Bill To		Ship To		
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO	
Customer ID#	NY023 (330A)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY	
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188	
Phone	954 900 1095			
Payment Due	NET 30	Delivery Date		
Salesperson	JW	Shipping Method	N/A	
Payment Terms	N/A	Shipping Terms	N/A	
Qty.	Item#	Description	Unit Price	Line Total
		NY23 BLDG 330A NORTH WEST CORNER 1ST FLOOR AC NOT WORKING ON THE 1ST FLOOR CARRIER (UNIT 5) MODEL ZP83KCETF5250 SN#15HC8243L UNIT NEEDS CLEANING AND A CONDENSER UNIT HAS MAJOR FREON LEAKS WELD ALL LINES REPLACE CONDENSER VACUUM SYSTEM RE CHARGE SYSTEM WITH R410A		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

REPLACE AIR FILTERS IN THE
EVAPORATOR

ACID WASH AND RINSE
CONDENSER COIL

ACID WASH AND RINSE
EVAPORATOR COIL

MATERIAL

1 EA SCROLL CONDENSER \$3500.00

15 LBS FREON R410A @ \$185.00 \$2775.00

PER LB

TOTAL MATERIAL \$6275.00

LABOR

24 HRS @ 205.00 PER HR \$4920.00

3 MEN 8 HRS EA

TOTAL \$11195.00

TOTAL \$11195.00

113
3255331

STACK
HEIGHT
HAUTEUR
DE PILE
ALTURA
DE APILAMIENTO

3

CAUTION
POTENTIAL
OF SERIOUS
INJURY
ALERTE DE RISQUE
D'UN SERIEUX
INJURIEUX

38AUZB08A0CJ-UHLMU

3615C94126

SERIAL # / NUMERO DE SÉRIE / # DE SERIE



3615C94126

SERIAL # / NUMERO DE SÉRIE / # DE SERIE

38AUZB08A0C5A0A0A0

MFG CODE / CODE DE FAB / CÓDIGO DE MFG



38AUZB08A0C5A0A0A0

MFG CODE / CODE DE FAB / CÓDIGO DE MFG

SERIAL # / NUMERO DE SÉRIE / # DE SERIE

3615C94126

RELEASE NUMBER / NUMERO DE SORTIE / # DE LIBERACION

009000289831

CARRIER CORPORATION
7310 West Morris Street
Indianapolis, IN 46231 U.S.A.

MADE IN MEXICO

50ES5000172 REV. 5

A

UNIT 5

**DRILL IN THIS
AREA ONLY!**

