

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 13986 CSS # 27446</b>
Description of Repairs	Removal of ballast and fluorescent lamp from four (4) fixtures in the second-floor women's bathroom. Replace with eight new LED ballast bypass lamps.  Removal of 2 fixtures damaged by overheated ballast in the third-floor women's bathroom and replace with two (2) flat panel 2x2 lay in LED lighting fixtures.
Diagnosis: Initial Work Order	Replace burned out light fixture in second floor woman's bathroom, and in the 3rd floor locker room.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8 hours @ 125.00 includes two (2) hours of diagnostic- Total Labor \$1000.00
Additional Material Cost to Perform Repairs	\$ 406.00
Total Cost of Repair	\$1406.00

MSL Electric, LLC

6555 GRAND AVE  
NY 11378

## Estimate

Date	Estimate #
7/1/2021	1254

Name / Address

---

International Support Group  
9050 Pine Blvd., Suite 150  
Pembroke Pines, FL 33024

Project  
NY0023  
200 Duane Road  
Bayside, NY 11359